

Table of Contents

1.0 Purpose and Need for Action.....	1
1.1 Introduction.....	1
1.2 Proposed Action.....	1
1.3 Purpose and Need	8
1.4 Issues.....	8
2.0 Alternatives.....	10
2.1 Introduction.....	10
2.2 Alternatives Considered.....	10
2.3 Other Alternatives Considered but Eliminated	13
2.4 No Action Alternative.....	13
2.5 Preferred Alternative.....	13
3.0 Affected Environment	18
3.1 Introduction.....	18
3.2 Geomorphology and Soils.....	18
3.3 Hydrology and Hydraulics.....	19
3.4 Water Quality.....	19
3.5 Cultural Resources and Traditional Cultural Properties	21
3.6 Vegetation and Wetland Resources	21
3.7 Fish and Wildlife.....	22
3.8 Threatened, Endangered, and Special Status Species.....	24
3.9 Socioeconomics	29
3.10 Visual and Aesthetic Resources.....	29
3.11 Air Quality and Noise	29
3.12 Net Water Depletions.....	30
3.13 Environmental Justice.....	30
3.14 Indian Trust Assets	30
4.0 Environmental Consequences.....	32
4.1 Introduction.....	32
4.2 Geomorphology and Soils.....	32
4.3 Hydrology and Hydraulics.....	32
4.4 Water Quality.....	32
4.5 Cultural Resources and Traditional Cultural Properties	33
4.6 Vegetation and Wetland Resources	33
4.7 Fish and Wildlife.....	34
4.8 Threatened, Endangered, and Special Status Species.....	34
4.9 Socioeconomics	37
4.10 Visual and Aesthetic Resources.....	37
4.11 Air Quality and Noise	38
4.12 Net Water Depletions.....	38
4.13 Environmental Justice.....	38

4.14	Indian Trust Assets	39
4.15	Irrecoverable Commitment of Resources.....	39
4.16	Cumulative Impacts	39
4.17	Summary of Effects and Site Suitability.....	41
4.18	Environmental Commitments	42
5.0	List of Preparers	44
6.0	Consultation and Coordination	45
7.0	References.....	46

Appendix A

Appendix B

List of Figures

1.1.	Project area location map.....	2
1.2.	Rio Bravo Subreach and project sites.....	4
1.3.	Rio Bravo North Site	5
1.4.	Rio Bravo South Site.....	6
1.5.	SDC Island Site.....	7

List of Tables

2.1.	Proposed Habitat Restoration Techniques	11
2.2.	Techniques Eliminated from Further Study.....	12
3.1.	Average Water Quality Data by Constituent for Central Avenue Gage.....	20
3.2.	Threatened (T), Endangered (E), Species of Concern (S), Candidate (C), and Proposed (P) Plant and Wildlife Species Known to Occur in Bernalillo County.....	24
4.1.	Environmental Consequences of Proposed Restoration Techniques on Environmental Resources under the Proposed Action and No Action Alternatives	41